
Тип 1.1




Исп.1


Dimensions in mm (inches). See Page 7 for mounting details.
49.9
(1.97)
43.0 CRS.
(1.69 CRS.)
12.9
(0.50)
61.0
(2.40)
50.0
(1.97)
52.8
(2.08)
OPTIONAL INTEGRAL AUXILIARY CONTACTS CAN BE FITTED HERE
POLARITY MUST BE OBSERVED WHEN MAGNETIC BLOWOUTS ARE FITTED
148.4 (CONTACTS OPEN)
(5.84)
6.5
(0.26)
49.6
(1.95)
63.5 (CONTACTS OPEN)
(2.50)
28.8
(1.13)
ACCESS HOLE (1 PER SIDE) FOR HOLDING SHAFT DURING KNOB TIGHTENING (VERSION WITHOUT LOCK ONLY)
48.0 CRS
(1.89 CRS)
73.9
(2.91)
70.0 (CONTACTS CLOSED OR READY TO CLOSE)
(2.76)
154.9 (CONTACTS CLOSED OR READY TO CLOSE)
(6.10)
Ø58.0
(2.28 DIA)
28.5 CRS
(1.12 CRS)
5.9
(0.23)
6.3MM SPADE TERMINALS FOR COIL CONNECTION
21.5
(0.85)
CONTACTS CAN BE FULLY ENCLOSED (OPTIONAL)
TWO M8 TERMINAL SCREWS, ONE TO BE POSITIONED ON EITHER SIDE, TO BE TIGHTENED WITHIN THE RANGE OF 8.5 TO 10 Nm


Тип 2.1



Исп.1


Dimensions in mm (inches). See Page 7 for mounting details.
54.2
(2.13)
50.0
(1.97)
29.2
(1.15)
POLARITY MUST BE OBSERVED WHEN MAGNETIC BLOWOUTS ARE FITTED
61.9
(2.44)
12.8
(0.50)
OPTIONAL INTEGRAL AUXILIARY CONTACTS CAN BE FITTED HERE
168.3 (CONTACTS OPEN)
(6.63)
36.0
(1.42)
62.5
(2.46)
63.5 (CONTACTS OPEN)
(2.50)
6.3MM SPADE TERMINALS FOR COIL CONNECTION
ACCESS HOLE (1 PER SIDE) FOR HOLDING SHAFT DURING KNOB TIGHTENING (VERSION WITHOUT LOCK ONLY)
48.0 CRS
(1.89 CRS)
6.3
(0.24)
174.8 (CONTACTS CLOSED OR READY TO CLOSE)
(6.88)
70.0 (CONTACTS CLOSED OR READY TO CLOSE)
Ø58.0
(2.28 DIA)
6.2
(1.97)
91.4
(3.60)
21.5
(0.85)
34.9 CRS
(1.38 CRS)
CONTACTS CAN BE FULLY ENCLOSED (OPTIONAL)
TWO M8 TERMINAL SCREWS, ONE TO BE POSITIONED ON EITHER SIDE, TO BE TIGHTENED WITHIN THE RANGE OF 8.5 TO 10 Nm

Тип 3.1






Исп.1



Исп.2

Тип 4.1







Исп.1



Исп.2

Тип 4.2



Ø57
62 (L1 Standard)
2
70
60
>UP<
M5 screw
Immersion
depth
8 mm min.
13 mm max.
irrespective of
mounting plate
and lock plate
5 max.
Main terminals
Immersion depth
of terminal screw
10 mm max.
70
71


Ø50
M8 /
M10
42
59



Исп.2


Тип 5.1





Исп.1

Тип 6.1



Тип 7.1

